

Make sure you have everything before you start soldering!


## CONNECTORS

MIDI Jack x2



J1, J2

Header .1" - 6P x4



P1, P2

## ACCESSORIES

Rack Screw Kit x1



Data Cable x2



Assembly instructions can be found at [division-6.com/seqexpand](http://division-6.com/seqexpand)

## PCBs / PANELS

Main PCB x1



PCB1

Front Panel x1



PCB2

## RESISTORS

220Ω 1/8W x4



R1, R2, R3, R4

## HARDWARE

Hex Standoff x4



M2.5 x 15mm

Silver Screw x4



M2.5

Black Screw x4



M2.5