

Make sure you have everything before you start soldering!


CAPACITORS

10µF Electrolytic x2



C1-C2

0.1µF Ceramic x2



C3-C4


LEDs

3mm - Blue x32




D1-16, D36-51

3mm - Yellow x26




D17-21, 24-30, 33, 52-56, 59-65, 68

3mm - Orange x2




D22, D57

3mm - Green x2




D23, D58

3mm - Red x4




D31-32, D66-67

3mm - White x2



D34, D69


3mm - True Green x2



D35, D70

DIODES

1N4148 x1



D71

CONNECTORS

3.5mm Jack x12




J1-12

-or-



Optional
Banana Jacks

10P Box Header x1



P3


PCBs / PANELS

Main PCB x1



PCB1

Front Panel x1



PCB2

RESISTORS

1K Trim Pot x2



R1, R2

Continued...

100Ω x10



R3-7, R16-20

1K x8



R8, R12-14, R21, R25-27

510Ω x2



R9, R22

4.7K x4



R10, R11, R23, R24

100K x4



R15, R28, R29, R30

BUTTONS / SWITCHES

Tact Switch - 6mm x42



S1-S42

ICs


PIC16F1783 x2



U1, U2

VOLTAGE REGULATORS


L4931CZ50 (5V) x1



VR1

Continued...

TL431 x2




VR2, VR3

HARDWARE

28 Pin IC Socket x2




Hex Standoff x4




Silver Screw x6



Black Screw x2



LED Spacer x70



ACCESSORIES

Euro Power Cable x1



Rack Screw Kit x1



 Assembly instructions can be found at division-6.com/dualsequencer

